

INTEGRATION INFORMATION

IBM OEM STORAGE PRODUCTS

PLATFORM(s) = RS6000
OPERATING SYSTEM(s) = AIX V3.2.1
SCSI INITIATOR(s) = Proprietary (supplied with platform)
DRIVE(s) AFFECTED = 0661-371 (P/N 93X2430)
0661-467 (P/N 73F8957)

CHANGES REQUIRED:

None but full function of the "RS6000 Advanced Diagnostics" is not available. System will return a "Protocol Error" if use of the unsupported functions is attempted.

Because of these limitations IBM does not recommend attaching these drives to the RS6000 platform.

COMMENTS:

The 0661 drives listed above require the AIX V3.2.1 level of operating system to allow attachment. The drives will not attach to the RS6000 platform running earlier levels of AIX.

Please note the operating temperature requirements of the drive which are specified in the relevant hardware specifications provided with evaluation units.

It is the responsibility of the OEM integrator to ensure the drive operates within these requirements in each application.